

Job Photo Report

Prepared Sep 5, 2026 · 3/3 sources included

Delivery coverage

3 of 3 charged sources produced a result (100%).

Sources received: 3 · Processed: 3 · Duplicate: 0 · Could not be read: 0 · Format not supported: 0 · No result recorded: 0

Every source received is accounted for and processed.

Service report

Purpose of the visit: bathroom demo and rebuild after a supply line failure under the vanity · S003 · site-notes.txt

Site: 2317 N Sawyer Ave, Unit 2, Chicago, IL 60647 · S003 · site-notes.txt

Date: 2026-08-03 · S003 · site-notes.txt

What the sources show

Statement issued by Riverside Plumbing & Remodel LLC on 08/03/2026 for Job RVP-2026-0142 at 2317 N Sawyer Ave, Unit 2, Chicago, IL 60647 lists materials and disposal charges totaling \$1,651.68, including Vanity, 30 in., white oak, Pressure-balance shower valve, Cement board, 3 ft x 5 ft, Porcelain floor tile, sq. ft., Thinset and grout, Dumpster, 10 yd., one week, Subtotal of \$1,498.12, and Sales tax (Chicago, 10.25%) of \$153.56. · stated in a document · S002 · materials-receipts-rvp-2026-0142.pdf

Under-sink plumbing diagram or rough-in schematic displaying a grey waste drain pipe with an S-trap configuration running horizontally to a wall outlet on the right, alongside a vertical tan pipe with an integrated valve on the left, positioned below an outlined basin silhouette against a tiled wall backdrop. · from an illustration, not a photograph · S001 · 01-under-sink-pipework-illustration.jpg

The drainage trap is disconnected from the sink basin, and water supply rough-in is incomplete. · from an illustration, not a photograph · S001 · 01-under-sink-pipework-illustration.jpg

Demo completed with old vanity, wall tile, and soft plywood removed. Subfloor patched, cement board installed, shower valve roughed in and pressure tested with no leaks after 30 minutes at line pressure. Tile set and grouted, vanity hung, and trim painted two coats. Open items include backordered mirror installation and hallway baseboard touch-up. Building shutoff valve remains original, stiff, and unreplaced. · stated in a document · S003 · site-notes.txt

Still open

Status stated in the sources for 1 of 2 items; 1 have no stated status.

Backordered mirror not installed; customer notified, ETA the week of Aug 17. · S003 · site-notes.txt

Baseboard in the hallway outside the bathroom was scuffed during demo, needs touch-up. · S003 · site-notes.txt

Handover

Engineer: _____ Date: _____

Customer: _____ Date: _____

This document is not signed. It is for both parties to sign together; it carries no electronic signature and makes no claim about legal or regulatory validity.

Overview

Sources processed: 3

Validated: 3

Exceptions: 0

Materials and receipts

State not stated · 1

1. S002 · materials-receipts-rvp-2026-0142.pdf · Work phase: procurement_and_disposal

Statement issued by Riverside Plumbing & Remodel LLC on 08/03/2026 for Job RVP-2026-0142 at 2317 N Sawyer Ave, Unit 2, Chicago, IL 60647 lists materials and disposal charges totaling \$1,651.68, including Vanity, 30 in., white oak, Pressure-balance shower valve, Cement board, 3 ft x 5 ft, Porcelain floor tile, sq. ft., Thinset and grout, Dumpster, 10 yd., one week, Subtotal of \$1,498.12, and Sales tax (Chicago, 10.25%) of \$153.56.

Source references: S002 · materials-receipts-rvp-2026-0142.pdf:p1; S002 · materials-receipts-rvp-2026-0142.pdf:p1

Source index

S001 · 01-under-sink-pipework-illustration.jpg · Source kind: image · Result status: included

S002 · materials-receipts-rvp-2026-0142.pdf · Source kind: pdf · Result status: included

S003 · site-notes.txt · Source kind: text · Result status: included

Items needing review

Backordered mirror not installed; customer notified, ETA the week of Aug 17. · S003 · site-notes.txt
Baseboard in the hallway outside the bathroom was scuffed during demo, needs touch-up. · S003 · site-notes.txt

Statement issued by Riverside Plumbing & Remodel LLC on 08/03/2026 for Job RVP-2026-0142 at 2317 N Sawyer Ave, Unit 2, Chicago, IL 60647 lists materials and disposal charges totaling \$1,651.68, including Vanity, 30 in., white oak, Pressure-balance shower valve, Cement board, 3 ft x 5 ft, Porcelain floor tile, sq. ft., Thinset and grout, Dumpster, 10 yd., one week, Subtotal of \$1,498.12, and Sales tax (Chicago, 10.25%) of \$153.56.

These are computed check results. No person has reviewed this delivery.

Draft prepared from supplied files. Confirm material decisions against the linked source evidence. No currency or unit conversion is performed.

Technical appendix

Everything below is the audit trail: what the job was configured to do and the exact digests behind each source. The report you need is above it.

Locked scope

Locked scope: unlocked
Requested goal: None
Applied goal: send-client
Selected sections: None
Emitted sections: scope, warnings, overview, photo_work_completed, photo_evidence, photo_issues, photo_materials, source_index, evidence_index, exceptions
Deterministic aggregation: no cross-document monetary total
Deterministic ranking: highest-confidence findings first
Warnings: None

Source index · Source SHA-256

S001 · 01-under-sink-pipework-illustration.jpg · d9e2f13d6a4c527c236c3758124ff44beb8ad63a29d9a7d52bcc6d68fdc95564
S002 · materials-receipts-rvp-2026-0142.pdf · 5a1159c6e929f0c0c8035a42a3f0cef35d9c540f281d52cfeb83f46c177b29e4
S003 · site-notes.txt · 44d878f7691de1dac472308cc1f8acdc5f47107959a34e3bb27de20cf55a335

Evidence index

ev_0496d612cce7e98cce07847adda16bc0 · issue · S003 · site-notes.txt:lines 19-20
ev_051ee2eb4fcc1d1571a33be577ab09dc · documentId · S003 · site-notes.txt:lines 1-1
ev_0c7f77d41cfc5e2657d400c6454a67d6 · observableDetail · S003 · site-notes.txt:lines 19-20
ev_122deb6fc74b09b92144ca67d919ef48 · summary · S001 · 01-under-sink-pipework-illustration.jpg:region 0.205,0.105,0.635,0.580
ev_213325466c89483f9e3178c9e8c828f1 · summary · S003 · site-notes.txt:lines 16-16
ev_235b3196b145f260956c95aa879f9c72 · observableDetail · S001 · 01-under-sink-pipework-illustration.jpg:region 0.205,0.105,0.635,0.580
ev_4c50157d6de886c2665579fe3a03fd32 · observableDetail · S003 · site-notes.txt:lines 22-23
ev_5728890d8058694cca3cf8f8cf305978 · observableDetail · S002 · materials-receipts-rvp-2026-0142.pdf:p1
ev_61bb33376af1544b4faa5366dedfac52 · summary · S003 · site-notes.txt:lines 12-13
ev_67a24e89720a81837ec0dcec041fe802 · observableDetail · S003 · site-notes.txt:lines 8-9
ev_84adc3865dc87f5d41408b2bee3259e2 · summary · S003 · site-notes.txt:lines 19-20
ev_af82500de0b93ee564c9db996183ad1b · summary · S002 · materials-receipts-rvp-2026-0142.pdf:p1
ev_be8e26094a7a453d3fa50285a86c6210 · observableDetail · S003 · site-notes.txt:lines 16-16
ev_e96b9b5fec73d72d2cf785bc98fc049a · observableDetail · S003 · site-notes.txt:lines 12-13
ev_f51c6f475cb8aaf35e4ba10531aa4bff · summary · S003 · site-notes.txt:lines 1-3

Bounded photo evidence

Original customer files are not copied into this evidence pack; only bounded, metadata-free image previews are included.

