

Site Documentation

Prepared 5 Sept 2026 · 4/5 sources included

Delivery coverage

4 of 5 charged sources produced a result (80%).

Sources received: 5 · Processed: 4 · Duplicate: 0 · Could not be read: 1 · Format not supported: 0 · No result recorded: 0

This delivery is partial: the sources listed below produced no result.

S002 · 03-mauerwerk-erdgeschoss.jpg · Our reader returned no usable result · The result did not match the required structure

Sources listed as not processed can be re-uploaded as a new job, or written to support with this job's reference for reprocessing or a refund of the affected scope.

Where the job stands

From the photographs: 4 open

4 actions written in your own notes are still open

Overview

Sources processed: 4

Validated: 4

Exceptions: 1

Issues and open items

Open · 4

1. S004 · arbeitsauftrag-aa-2026-0417.pdf · Work phase: Bauabschnitt 2, Nordfassade und Erdgeschoss

For 'Bauabschnitt 2, Nordfassade und Erdgeschoss' at 'Wohnanlage Kastanienhof, Kastanienallee 22–26, 63450 Hanau', items 1 to 4 and 6 are marked 'erledigt': Gerüststellung Nordfassade (310,00 m²), Bewehrung Bodenplatte Bauteil B einbauen (1.240 kg), Mauerwerk Erdgeschoss (86,00 m²), Elektro-Leerrohre in Bodenplatte verlegen (180,00 m), and Innenausbau Musterwohnung, Endreinigung (1 psch). Pos. 5 WDVS-Dämmung Nordfassade (310,00 m²) is marked 'teilweise' ('Dämmung nur bis Achse C ausgeführt'), and Pos. 7 Fensterelemente EG einbauen (12 Stk) is 'offen'.

Source references: S004 · arbeitsauftrag-aa-2026-0417.pdf:p1; S004 · arbeitsauftrag-aa-2026-0417.pdf:p1; S004 · arbeitsauftrag-aa-2026-0417.pdf:p1

2. S005 · bautagebuch-kw34.txt · Work phase: Rohbau / Ausbau

For Kalenderwoche 34/2026, work included Gerüststellung Nordfassade abgeschlossen (310 m² Arbeitsgerüst), Bewehrung Bodenplatte Bauteil B abgenommen, Mauerwerk Erdgeschoss (86 m² KS-Plansteine 17,5 cm), Elektro-Leerrohre (180 m verlegt), WDVS-Dämmung Nordfassade executed up to Achse C (ca. 210 von 310 m²), and Innenausbau Musterwohnung fertiggestellt und endgereinigt.

Source references: S005 · bautagebuch-kw34.txt:lines 11-11; S005 · bautagebuch-kw34.txt:lines 38-42; S005 · bautagebuch-kw34.txt:lines 19-20; S005 · bautagebuch-kw34.txt:lines 27-28; S005 · bautagebuch-kw34.txt:lines 32-32; S005 · bautagebuch-kw34.txt:lines 1-1; S005 · bautagebuch-kw34.txt:lines 24-25; S005 · bautagebuch-kw34.txt:lines 1-1; S005 · bautagebuch-kw34.txt:lines 17-18; S005 · bautagebuch-kw34.txt:lines 33-35; S005 · bautagebuch-kw34.txt:lines 5-5

3. S001 · 01-geruest-nordfassade.jpg · Work phase: scaffolding and structural shell construction

Extensive multi-tier modular scaffolding covers the building facade, with timber shuttering/formwork visible at the upper levels and protective sheeting applied at the roof edge. A security mesh perimeter fence encloses the construction base, fronted by a paved parking area containing parked cars and secured bicycles.

Source references: S001 · 01-geruest-nordfassade.jpg:region 0.040,0.000,0.950,0.720; S001 · 01-geruest-nordfassade.jpg:region 0.000,0.000,1.000,1.000

4. S003 · 06-daemmung-fassade.jpg · Work phase: facade insulation and window installation

Yellow mineral wool insulation panels are affixed to the facade with red disc insulation anchors. Metal brackets and vertical subframe profiles are installed across the elevation. Double-glazed window units branded 'PLAFEN' are set in place, retaining protective tape along the PVC frames. A vertical white pipe is mounted down the left section of the wall.

Source references: S003 · 06-daemmung-fassade.jpg:region 0.020,0.000,0.980,1.000; S003 · 06-daemmung-fassade.jpg:region 0.020,0.000,0.980,1.000; S003 · 06-daemmung-fassade.jpg:region 0.470,0.100,0.310,0.510

Still open

Fensterelemente EG, 12 Stueck, Liefertermin unbestaetigt · S005 · bautagebuch-kw34.txt

WDVS-Restflaeche ab Achse C, ca. 100 m2 · S005 · bautagebuch-kw34.txt

Kernbohrung Achse D, Nachtrag 1.500 Euro nicht beauftragt · S005 · bautagebuch-kw34.txt

Wasserschaden Kellerabgang, Ursache und Kostentraeger ungeklaert · S005 · bautagebuch-kw34.txt

Source index

S001 · 01-geruest-nordfassade.jpg · Source kind: image · Result status: included

S002 · 03-mauerwerk-erdgeschoss.jpg · Source kind: image · Result status: exception

S003 · 06-daemmung-fassade.jpg · Source kind: image · Result status: included

S004 · arbeitsauftrag-aa-2026-0417.pdf · Source kind: pdf · Result status: included

S005 · bautagebuch-kw34.txt · Source kind: text · Result status: included

Items needing review

S002 · 03-mauerwerk-erdgeschoss.jpg: Our reader returned no usable result

S002 · 03-mauerwerk-erdgeschoss.jpg: schema_invalid

Work order AA-2026-0417 for Bauabschnitt 2 (Nordfassade und Erdgeschoss) shows scaffolding, reinforcement, masonry, electrical conduit installation, and final cleaning of the show flat completed ('erledigt'). External thermal insulation (WDVS-Dämmung) is partially completed up to axis C, while installation of 12 ground-floor window elements remains open due to delivery delay ('Lieferverzug'). For Kalenderwoche 34/2026, work included Gerueststellung Nordfassade abgeschlossen (310 m2 Arbeitsgeruest), Bewehrung Bodenplatte Bauteil B abgenommen, Mauerwerk Erdgeschoss (86 m2 KS-Plansteine 17,5 cm), Elektro-Leerrohre (180 m verlegt), WDVS-Daemmung Nordfassade executed up to Achse C (ca. 210 von 310 m2), and Innenausbau Musterwohnung fertiggestellt und endgereinigt.

These are computed check results. No person has reviewed this delivery.

Draft prepared from supplied files. Confirm material decisions against the linked source evidence. No currency or unit conversion is performed.

Technical appendix

Everything below is the audit trail: what the job was configured to do and the exact digests behind each source. The report you need is above it.

Locked scope

Locked scope: unlocked
Requested goal: None
Applied goal: send-client
Selected sections: None
Emitted sections: scope, warnings, overview, photo_work_completed, photo_evidence, photo_issues, photo_materials, source_index, evidence_index, exceptions
Deterministic aggregation: no cross-document monetary total
Deterministic ranking: highest-confidence findings first
Warnings: None

Source index · Source SHA-256

S001 · 01-geruest-nordfassade.jpg · cc3f1f185307cfba1632e0dcbae0441d0a670de32cb1f64daa0947b58b39bf7
S002 · 03-mauerwerk-erdgeschoss.jpg · f0 added 2917feab5313ad89648b037eaace941f1ed123e18ac41e287b812c457e4
S003 · 06-daemmung-fassade.jpg · 41158d6be6803616d719d1042a08e40689fe0235a3280add31086f4692010c32
S004 · arbeitsauftrag-aa-2026-0417.pdf · 1e0ecb3877739fc7f9c17c2f396e145e35a2a1d4c45d699a62d61f79dad716af
S005 · bautagebuch-kw34.txt · 2ab3a891f1eebdddcb865da3f2bdf291db3d2ed05fefcbdb85994d061976ca8d8

Evidence index

ev_0ca10387d1369cefceb3e34998556286 · observableDetail · S005 · bautagebuch-kw34.txt:lines 11-11
ev_1e2b7f09e41552b08fb71b53a0af155f · summary · S004 · arbeitsauftrag-aa-2026-0417.pdf:p1
ev_26b59c67e38834721d8df4284cd81e39 · summary · S005 · bautagebuch-kw34.txt:lines 38-42
ev_3a04aa6bdd7f8ccb67f389c1729f519f · summary · S005 · bautagebuch-kw34.txt:lines 19-20
ev_4710323280d0fcebc48f9b089e37f76 · issue · S005 · bautagebuch-kw34.txt:lines 27-28
ev_4e858378ca2a741fccb730a03df81ce0 · observableDetail · S005 · bautagebuch-kw34.txt:lines 32-32
ev_66728e3780bde35782f2c47c7af21e93 · documentId · S005 · bautagebuch-kw34.txt:lines 1-1
ev_670b88c6cdb3dc61337161b907634f9e · observableDetail · S005 · bautagebuch-kw34.txt:lines 24-25
ev_6e1af33ef9c9774e9727c80f2f4f71a9 · observableDetail · S003 · 06-daemmung-fassade.jpg:region 0.020,0.000,0.980,1.000
ev_81ce3713388a9863ec71600546bb13c8 · summary · S003 · 06-daemmung-fassade.jpg:region 0.020,0.000,0.980,1.000
ev_953581a5fb63931e2f216b31b0a96ee0 · sourceKind · S005 · bautagebuch-kw34.txt:lines 1-1
ev_b144e02b5b7f1c898aa69d503c4e6042 · observableDetail · S005 · bautagebuch-kw34.txt:lines 17-18
ev_b9190258ef239df4a6fb6ef131c0ad85 · observableDetail · S004 · arbeitsauftrag-aa-2026-0417.pdf:p1
ev_ce17ab1f5397687560effeabd610e863 · issue · S005 · bautagebuch-kw34.txt:lines 33-35
ev_db3766ff5e69a4c9e40eb2d149d968e6 · observableDetail · S001 · 01-geruest-nordfassade.jpg:region 0.040,0.000,0.950,0.720
ev_dd72214680f8f5d1f76532288df3d71f · issue · S004 · arbeitsauftrag-aa-2026-0417.pdf:p1
ev_e8194e4afb52454d7e378d237e6e9df2 · observableDetail · S005 · bautagebuch-kw34.txt:lines 5-5
ev_f253713fa9d3c1821ef97c2ee0a06a9e · observableDetail · S003 · 06-daemmung-fassade.jpg:region 0.470,0.100,0.310,0.510
ev_faeded3bd39f65ba6aa02a94f48091b9 · summary · S001 · 01-geruest-nordfassade.jpg:region 0.000,0.000,1.000,1.000

Bounded photo evidence

Original customer files are not copied into this evidence pack; only bounded, metadata-free image previews are included.


S001 · 01-geruest-nordfassade.jpg

image · cc3f1f185307



S002 · 03-mauerwerk-erdgeschoss.jpg

image · f0fdd2917fea



S003 · 06-daemmung-fassade.jpg

image · 41158d6be680

